

Recent Topics related to Seismic Safety of Dams

September 24, 2009

Tatsuo OHMACHI


Professor, Tokyo Institute of Technology

Contents

1. Recent earthquake damage to dams and lessons learnt
1999 Chi-chi, Taiwan, 2004 Niigata-chuetsu, Japan
2008 Iwate-Miyagi inland, Japan, and 2008 Wenchuan, China
2. “Guidelines for seismic safety evaluation of dams(draft)”(2005)

The Chi-chi Earthquake (M7.7)


- The Earthquake struck Taiwan at 1:47 a.m. (local time) on Sept. 21,1999, causing the collapse of Shih-Kang Dam constructed in 1977.



Shih-kang Dam

- The dam was a 357 m long concrete gravity dam, equipped with 18 spillway gates and 2 sediment flushing gates.
- **Mainly due to seismic faulting crossing the dam foundation, the right half of the dam was crushed to pieces, and offset about 8.5m**
- No casualty was reported, as a result of the dam break.





18 spillway gates were numbered from the left end No.1 to the right end No.18.

Vertical and horizontal cracks were found, here and there, on the surface of concrete base and piers.

Transverse Cross Section of Shih-kang Dam (Spillway section)

- 1) Oct. 9 and 12, 1999
- 2) Feb. 26, 2000
- 3) Sep. 20, 2000

Dam crest

3-component sensor


PC for monitor and recorder

Amplifier

10 9 '99

Shih-kang Dam was restored and has been in use still now.

Micro-tremor measurement was conducted three times along the dam crest.





LA: Left Abutment
 S1+S2: Sluice
 (sediment flushing gates)

No.1 ~ No.18
 Spillway gates

**Micro-tremors Observed
 after the 1999 Earthquake
 (1st Measurement)**
 (max=1 is 10 μ m)

RA: Right Abutment



1st + 2nd Sequences


1st + 2nd + 3rd and 4th Sequences

Grout Takes in the Restoration of Shih-kang Dam

Left abutment

AXIS DIRECTION

Severe damage



Vibration period distribution along the dam axis

Lessons from the 1999 Chi-chi Earthquake

- 1. Shih-kang Dam was totally collapsed by surface rupturing of the seismic fault crossing the dam body.**
- 2. Despite the devastating damage to the dam body, followed by uncontrolled outflow discharge, no casualty was reported, which was very lucky.**
- 3. Micro-tremor measurement applied to the dam has proved to be useful and effective not only for detecting the damage, but also finding effects of the restoration.**



2004 Niigata-chuetsu EQ

1: Asagawara Dam

2: Yamamoto Dam

3: Shin-yamamoto Dam

Fault Plane



Asagawara Dam (Built in 1945)
Crest Length : 291.80m
Dam Height : 37m
Volume : 520,900m³
Slopes : Upstream 1 : 2.8~3.0
Downstream 1 : 2.0~2.5



Cracks along the crest of Asagawara dam which is a 37m-high zoned fill-dam constructed in 1945.

Downstream

Upstream

Trench Investigation at Asagawara Dam



Yamamoto Dam

Shin-Yamamoto Dam with a semi-circular dam axis

stagnation

Uplift of 0.60m at Inlet


Uplift of 0.55m

Main Flow

Uplift of 0.50m at Spillway

Uplift of 0.64cm at Spillway

0 200m






Thick Layer of
Sedimentation

Riprap

**Upstream View of Shin-Yamamoto Dam
(Left-half Side)**



Boiled Sand indicating Liquefaction



Shin-Yamamoto Dam(1990)

- Crest Length : 1,360m
- Dam Height : 42.4m
- Volume : 2,300,000m³
- Slopes :
 - Upstream Side: 1 : 3.4
 - Downstream Side: 1 : 2.1


This dam was restored by removing loosened/liquefied portions followed by re-banking with good materials and careful compaction.

Standard Cross Section of Shin-Yamamoto Dam

Lessons from the 2004 Niigata-chuetsu Earthquake, Japan

1. Strong shaking due to near field earthquake motions causes damage to fill dams such as cracks, settlement, sliding and even liquefaction or sand boiling.
2. Such damage is not always fatal to dam safety, but requires prompt emergency management such as dewatering the reservoir, warning to downstream areas, and investigation of causes and effects of the damage.
3. Sedimentation in a reservoir is sometimes harmful to a dam equipped with drain layers, because thick sedimentation leads to loss of the drain function.

Outline of the earthquake and Aratozawa dam



Aratozawa Dam

Background

Iwate-Miyagi inland earthquake

The earthquake (M7.2) occurred in 2008
The dead and missing were 23 people

Aratozawa dam

Constructed: 1994
Type: Center Clay-core Rock-fill Dam
Height: 74.4m

Damage


40cm settlement of the dam crest
Fortunately the dam escaped serious damage

40cm Settlement




Outline of strong motion records

Acceleration time history (Stream)




3 component Seismometers
(Sampling frequency 100Hz)




Peak Accelerations(gal)

	Stream	Dam-axis	Vertical
Crest	525	535	622
Mid-core	535	478	470
Gallery	1024	899	691



Transfer Functions of the dam

Transfer function between the gallery and crest (crest/gallery)




The peak period of the dam was 0.7sec/1.2 sec during the main shock and about 0.4sec in other smaller earthquakes.



As the change in the period during the main shock was remarkable, detailed analysis was conducted using running spectra.

Running spectra during the main shock

Running spectral ratio (crest/gallery)




The peak period was first 0.4 sec and suddenly elongated to 1.2sec by strong shaking and later shortened again to 0.5sec.



This is evidently the nonlinear response of a rockfill dam.



Shear Modulus vs. Shear Strain



Lessons from the 2008 Iwate-Miyagi Inland Earthquake

1. During the main shock of the 2008 Iwate-Miyagi Inland earthquake, Aratozawa dam was severely shaken, nevertheless the dam escaped serious damage.
2. During the main shock, the acceleration exceeded 10 m/s^2 at the gallery, inducing large shear strains in excess of 10^{-3} .
3. Due to the large strains, the shear modulus G showed a remarkable decrease from the initial shear modulus G_0 . As a result of the decrease in G , wave velocity was reduced and the vibration period of the dam was elongated.
4. Towards the end of the main shock, the modulus G in the core showed a gradual increase, but remained below G_0 .

中国四川省 汶川地震 (Wenchuan EQ, M8.0) May 12, 2008 竜門山断層 (Longmenshan Fault, L ≐ 300km)





Downstream face



Upstream face


Tunnel spillway

Shapai(沙牌) Dam:

RCC Arch dam
H=130m、L=250m
Constructed in 2003
Epicentral Dist. 30km

Earthquake Damage:

No damage to dam body,
but some damage to
spillway, elevator tower,
plumb line, etc. **Moreover,**




Elevator tower



Plumb line

Shapai powerhouse was severely damaged mainly due to landslides.



Powerhouse located in a narrow canyon




Penstock was broken by rock falls, inundating the canyon with water.



**Power Capacity:
36MW**

Inundated powerhouse (left) and switchyard (right)



Plan of Futang Dam (H=31m, L=189.5m)



Futang Dam and Landslide in its Neighborhood

Lessons from the 2008 Wenchuan Earthquake

- 1. A fault rupture over an extended length should be considered in the seismic hazard modeling of a dam; which is quite different from a point source modeling traditionally considered.**
- 2. Reliable post-earthquake functionality of flow control equipment, e.g., gates, valves, controls, etc., is essential for dam safety and is necessary for the safe regulation of downstream flows.**
- 3. Landslides and rock fall can have a high impact on powerhouses, power conduits, and appurtenant structures. Under some circumstances, it is advisable to have a powerhouse located underground rather than on the ground surface or to provide barriers for protection against potential rock fall.**
- 4. Dam and reservoir monitoring instrumentation should have sufficient seismic resistance to survive extreme events and to record and transmit data during and after a big earthquake.**

JSCE Proposal on Earthquake Resistance of C. E. Structures

- Following the 1995 Kobe earthquake, the Japan Society of Civil Engineers (JSCE) issued three times the Proposal.
- The first in May, 1995, the second in January, 1996, and the third in June 2002 .
- The Proposal covers a wide range from review and upgrading of seismic codes, seismic diagnosis and reinforcement to seismic safety planning.
- One of the main targets of the Proposal was to revise seismic codes, especially those of earthquake motions.

Earthquake motions to be considered in seismic design, proposed by JSCE

- 1) Two types of earthquake motions should be considered in seismic design of civil engineering structures; Level 1 and 2 motions.
- 2) Level 1 (L1) motion covers motions of moderately high intensity, while Level 2 (L2) motion addresses strong motion of extremely high intensity of the nature experienced in Kobe city during the 1995 earthquake.
- 3) For the L2 motion, structures are allowed to undergo some damage as long as collapse and loss of life are prevented.

Safety Requirements of Dams Subjected to Level 2 Motions

Guidelines for Seismic Safety Evaluation (Draft), issued by MLIT in 2005

- Irrespective of dam type, a dam subjected to the L2 motion is required ;
 - (1) to maintain its *capability of water storage* during and after the earthquake, and
 - (2) to remain *within repairable damage* even if it suffers earthquake-induced damage.
- The statement (1) is paraphrased into
 - (3) *not to release uncontrolled outflow discharge* from reservoir.

Thank you for your attention